## HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

HAER MASS 12-BRock 2-

## FIELD STREET BRIDGE

HAER No. MA-136

Spanning the Old Colony Railroad at Field Street Brockton Plymouth County Massachusetts

Martin Stupich, Photographer, May 1996, except as noted.

MA-136-1	General view of setting, showing bridge and backs of buildings fronting Montello Street; view to south.
MA-136-2	General view from track grade showing north elevation of truss and abutments; view to southeast.
MA-136-3	General view from track grade showing south elevation of truss and abutments; view to northwest.
MA-136-4	Oblique view of south elevation showing sidewalk and railing; view to north.
MA-136-5	General view across bridge to northeast.
MA-136-6	General view across bridge to southwest.
MA-136-7	Detail of north truss; view to west.
MA-136-8	Detail of south truss diagonals with easterly end of north truss visible beyond; view to northeast.
MA-136-9	Detail of underside of south truss upper chord at eastern endpost, showing box-section configuration with lacing inside; view to northeast.
MA-136-10	Detail of south truss, eastern endpost, showing box-section configuration with lacing inside; view to northeast.
MA-136-11	Detail of south truss upper chord connection to eastern endpost; view to north.
MA-136-12	Detail of south truss interior panels; view to west.
MA-136-13	Detail of south truss, underside of easternmost outward-sloping diagonal, view downward to northeast.
MA-136-14	Detail of east abutment, showing stepped granite southern wingwall; view to north.

## INDEX TO PHOTOGRAPHS FIELD STREET BRIDGE HAER No. MA-136 (page 2)

MA-136-15	Detail of west end of bridge, south elevation, showing underside of deck and floor beams; view to north. (Note 1892 Howard Street Bridge visible to north.)
MA-136-16	Detail of south truss, showing sidewalk brackets and gusseted railing posts; view to northeast.
MA-136-17	Detail of south truss lower chord at western endpost connection, showing bearing seat on abutment; view upward and northwest.
MA-136-18	Detail of floor system, showing north truss lower chord, easterly floor beams, stringers, and lower lateral bracing; view to east.
MA-136-19	General view from railroad grade showing east abutment, easterly floor beams,

